


Appln No. 10/562,171
Amdt. Dated August 6, 2008
Response to Office Action of February 6, 2008
Replacement Sheet # 1

**Typical fault current characteristics
at a substation LV side**



PRIOR ART

Appln No. 10/562,171
Amdt. Dated August 6, 2008
Response to Office Action of February 6, 2008
Replacement Sheet # 2

Transient fault current per transformer
SC-FCL Design option 2





Fig. 2

PRIOR ART

Appln No. 10/562,171
Amdt. Dated August 6, 2008
Response to Office Action of February 6, 2008
Replacement Sheet # 3



Appln No. 10/562,171
 Amdt. Dated August 6, 2008
 Response to Office Action of February 6, 2008
 Replacement Sheet # 4




Fig. 4
 PRIOR ART